| Winter Course Schedule   |  |   |   |
|--|--|---|---|
| JANUARY  | FEBRUARY   | MARCH   | APRIL   |
| JAN 10, 11, 12<br>LOCATION: <u>NIPIGON</u><br>DEADLINE: JAN 8<br>??  | FEB 7, 8, 9 LOCATION: DRYDEN DEADLINE: FEB 3 Practices Procedures for WT Plants (0.7 CEU) Tapping of Water Mains (0.7 CEU) Trenching and Excavation Safety (0.7 CEU)   | MAR 5-9<br>LOCATION: <u>TIMMINS</u><br>DEADLINE: FEB 9<br>OWWCO EXAM: MAR 9<br>OIT - WT/WD I-II-III (2.6 CEUs)  | APR 9-12 LOCATION: WINNIPEG EXAM: APR 13 Water Training for the Indigenous Leadership Development Institute  APR 17-18 LOCATION: DRYDEN DEADLINE: APR 13 Coagulation and Flocculation (0.7 CEU) UV and Ozone Disinfection (0.7 CEU)  APR 23-27 LOCATION: DRYDEN DEADLINE: MAR 27 OWWCO EXAM: APR 27 OIT - WT/WD I-II-III (2.6 CEUS) |
| JAN 15, 16, 17 LOCATION: DRYDEN DEADLINE: DEC 18 Coagulation Flocculation (0.7 CEU) Filtration (0.7 CEU) Processes for WT Plants (0.7 CEU) |  | MAR 12, 13, 14 LOCATION: DRYDEN DEADLINE: MAR 9 Piping and Water Main Installation (0.7 CEU) Pumping Stations and Hydraulics (0.7 CEU) Water Leak Detection (0.7 CEU) |   |
|  | FEB 12-16 LOCATION: DRYDEN DEADLINE: JAN 16 OWWCO EXAM: FEB 16 OIT - WT/WD I-II-III (2.6 CEUs)  FEB 27, 28, MAR 1 LOCATION: TORONTO DEADLINE: Safety in the Workplace (0.5 CEU) DAY 1 Safety in the Workplace (0.5 CEU) DAY 2 Lock Out Tag Out and WHMIS (0.7 CEU) |   |   |
| JAN 22-26<br>LOCATION: DRYDEN<br>DEADLINE: DEC 22<br>OWWCO EXAM: JAN 26<br>OIT - WT/WD I-II-III (2.6 CEUs)                                 |  | MAR 19-23 LOCATION: DRYDEN DEADLINE: FEB 23 OWWCO EXAM: MAR 23 OIT - WT/WD I-II-III (2.6 CEUs)  |   |
| JAN 30, 31 LOCATION: DRYDEN DEADLINE: JAN 26 Safety in the Workplace (0.5 CEU) Lock Out & TDG (0.7 CEU)                                    |  |   |   |