March to June Course Schedule			
MARCH	APRIL	MAY	JUNE
MAR 2 - 6 ELC in Dryden (WEEK 1) MAR 11, 12 Intro to OM of WD Systems (0.4 CEU) Practices and Procedures for WD Systems (0.7 CEU) LOCATION: DRYDEN DEADLINE: MAR 6 MAR 18, 19 Computer Literacy with Microsoft Office LOCATION: DRYDEN DEADLINE: MAR 13 MAR 18, 19 Intro to OM of WD Systems (0.4 CEU) Practices and Procedures for WD Systems (0.7 CEU) LOCATION: NIPIGON DEADLINE: MAR 13 MAR 23 - 27 OIT (2.6 CEUS) LOCATION: DRYDEN DEADLINE: MAR 6 OWWCO EXAM: MAR 27 MAR 30 - APR 3 ELC in Dryden (WEEK 2)	APR 7, 8, 9 Safety in the Workplace (0.5 CEU) Pumping Stations and Hydraulics (0.6 CEU) Tapping of Water Mains (0.6 CEU) LOCATION: DRYDEN DEADLINE: APR 3 APR 14, 15, 16 Safety in the Workplace (0.5 CEU) Pumping Stations and Hydraulics (0.6 CEU) Tapping of Water Mains (0.6 CEU) LOCATION: NIPIGON DEADLINE: APR 10 APR 20 - 24 WT/WD I-II-III (2.6 CEUS) LOCATION: DRYDEN DEADLINE: APR 3 OWWCO EXAM: MAR 24 APR 27, 28 MS Excel LOCATION: THUNDER BAY DEADLINE: APR 24	MAY 5, 6, 7 Trenching and Excavation Safety (0.7 CEU) Piping and Water Main Installation (0.7 CEU) Controlling Corrosion (0.7 CEU) LOCATION: DRYDEN DEADLINE: MAY 1 MAY 12, 13, 14 Trenching and Excavation Safety (0.7 CEU) Piping and Water Main Installation (0.7 CEU) Controlling Corrosion (0.7 CEU) LOCATION: NIPIGON DEADLINE: MAY 8 MAY 25 - 29 OIT (2.6 CEUS) LOCATION: DRYDEN DEADLINE: MAY 8 OWWCO EXAM: MAY 29	JUN 9, 10, 11 Backflow Prevention and Cross Connection (1.3 CEUS) Safety in the Workplace (0.5 CEU) LOCATION: DRYDEN DEADLINE: JUN 5 JUN 15 - 19 WT/WD I-II-III (2.6 CEUS) LOCATION: DRYDEN DEADLINE: MAY 29 OWWCO EXAM: JUN 19 JUN 23, 24, 25 Backflow Prevention and Cross Connection (1.3 CEUS) Safety in the Workplace (0.5 CEU) LOCATION: NIPIGON DEADLINE: JUN 19